

HYDRANT FLOW TEST

Test Hydrant

Test Date 02/05/2006

Time of Test 9:00 AM

System ID No: 2004

Hydrant Number C-008

Address 900 Center Ave X Rockway - San Anselm X Rockway San Anselmo

Hydrant Location NW Corner

Hyd. Valve Loc. In Manhole on Rockway

Map Page _____

Static Pressure 95

Residual Press 65

Test Code _____

Needs Maint? _____

Test Performed by Jame Onoon

Test Company San Demo Water District

Flow Hydrant(s)

Hydrant #	Diameter	Coeffecient	Pitot PSI	Flush Time (Min)	Flow (GPM)	Water Used (Gal)
201	2.50	0.90	42.00	15.00	1,088	16,320
Totals:					1,088	16,320
Pressure Zone: <u>4</u>					Flow at 20 PSI	1,784

Test Comments

Flushing Information

	Time to Clear	5	Temperature	52
	Initial Color	Gray	pH Level	7.1
	Initial CL2	0.32	Initial Turbidity	2
	Final CL2	0.15	Final Turbidity	1

